



Figure 1: Hillslope seepage dominated by sedges and grasses



Figure 2: Hillslope seepage dominated by rudimentary and pioneer



Figure 3: Anthropogenic Open Excavation Technosols, Cullinan 1000, associated with a historic borrowpit.



Figure 4: The result of agriculture and road infrastructure run-off.



Figure 5: The view of the existing Dorstfontein mining infrastructure





Figure 6: Transformed agricultural land with DCM East operations in the backdrop



Figure 7: Evidence of in-situ soil erosion along the non-perennial stream at DCM West mine



Figure 8: Existing discard dump that is meant to be expanded



Figure 9: Terrain across which the proposed conveyor is to traverse (taken from the top of the Discard Dump)





Figure 10: Powerlines within the study area



Figure 11: The view of the existing discard dump

